HA135 0410 23-LANC 4-

## HISTORIC AMERICAN BUILDINGS SURVEY

## INDEX TO PHOTOGRAPHS

Addendum to:
DEVOL-DALLOW HOUSE
Lancaster
Fairfield County
Ohio

HABS No. OH-413

Photographs	рy	Perry	Ε.	Borchers	of	the	Ohio	State	University,	1957.

OH-413-1	NORTH FACADE  Copy photograph of photogrammetric plate  LC-HABS-GS07-T-810-401R.
ОН-413-2	SOUTH (NEAR) FACADE  Copy photograph of photogrammetric plate LC-HABS-GS07-T-810-402R.
OH-413-3	MAIN ENTRANCE, NORTH FACADE  Copy photograph of photogrammetric plate  LC-HABS-GS07-T-810-403L.
OH-413-4	NORTH AND WEST FACADES, ANGLED Copy photograph of photogrammetric plate LC-HABS-GS07-T-810-404R.
OH-413-5	ENTRANCE AND STAIRWAY HALL  Copy photograph of photogrammetric plate  LC-HABS-GS07-T-810-405L.
OH-413-6	ENTRANCE HALL, LOOKING TOWARDS ENTRANCE Copy photograph of photogrammetric plate LC-HABS-GS07-T-810-406R.
OH-413-7	SECOND FLOOR ARCHWAY FROM DEMOLISHED EFFINGER HOUSE Copy photograph of photogrammetric plate LC-HABS-GS07-T-810-407L.
OH-413-8	DOORWAY OF NE PARLOR  Copy photograph of photogrammetric plate  LC-HABS-GS07-T-810-408R.
OH-413-9	MANTEL OF NE PARLOR  Copy photograph of photogrammetric plate LC-HABS-GS07-T-810-409L.

DEVOL-DALLOW HOUSE HABS No. OH-413 Index to Photographs (Page 2)

ОН-413-10	FIREPLACE OF SE PARLOR  Copy photograph of photogrammetric plate  LC-HABS-GS07-T-810-410L.
OH-413-11	STAIRWAY AT SECOND FLOOR, SHOWING EFFINGER DOOR Copy photograph of photogrammetric plate LC-HABS-GS07-T-810-411R.
OH-413-12	STAIRWAY FROM SECOND FLOOR LEVEL Copy photograph of photogrammetric plate LC-HABS-GS07-T-810-412R.
OH-413-13	VERTICAL VIEW UP CIRCULAR STAIRWAY  Copy photograph of photogrammetric plate  LC-HABS-GS07-T-810-413L.